APPENDIX B

CENTRAL BAY

Battelle. 1994a. Ecological evaluation of proposed dredged material from the Port of Richmond maintenance and deepening program. Richmond, California: Port of Richmond.

Battelle. 1994b. The Remedial Investigation of Marine Sediment at the United Heckathorn Superfund Site. Prepared for U.S. Environmental Protection Agency by Battelle/Marine Science Laboratory. Sequim, WA. February, 1994.

Brown, B., J.A. Ward, N.P. Kohn, B.N. Bjornstad, E.A. Crecelius. 1990.Environmental evaluations for deepening of Richmond Harbor and Santa Fe channels.Task 4: Chemistry Program. San Francisco: U.S. Army Corps of Engineers SanFrancisco District.

ESA. 1988. Dredge sediment evaluation Point Molate fuel pier, Richmond, CA. San Bruno: U.S. Navy Western Division.

EVS Consultants. 1990. Bioassay, bioaccumulation, and chemical testing of sediments from Richmond inner and outer harbors. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

EVS Consultants. 1991. Chemical and toxicological analyses of sediments from Castro Cove, San Francisco Bay. Three volumes. Richmond, California: Chevron USA.

Harding, Lawson and Associates (HLA). 1986. Revised draft site characterization and remedial action plan. United Heckathorn site, Richmond, CA. U.S. Environmental Protection Agency.

Hart Crowser Inc. 1992. Draft remedial investigation, volume I. Port of Richmond Shipyard, No. 3 scrap area site. Richmond, California.

Hart Crowser, Inc. 1993. Final remedial investigation report, volume I. Port of Richmond Shipyard No. 3 scrap area site (Ref. # J-6068).

Jefferson Associates. 1987. Draft environmental impact report and appendices. Chevron USA Richmond refinery deep water outfall project, Volume I, Volume II, Volume III.

Richmond, California: City of Richmond and California Regional Water Quality Control Board.

Kennedy, Jenks, Chilton. 1990. Final remedial investigation report: Liquid Gold site, Richmond outer harbor, Richmond, CA. Vol 2. San Francisco: Southern Pacific Trans Company.

Kennedy/Jenks Consultants. 1995. Final marsh sediment post-remediation confirmation sampling report, Liquid Gold site, Richmond, CA. San Francisco: Southern Pacific Transportation Company.

Levine Fricke. 1985. Point Isabel remedial program, report of field sampling activities and results, Santa Fe Land Improvement Company. San Francisco: California Regional Water Quality Control Board, San Francisco Bay Region.

Levine-Fricke. 1990. Remedial Investigation, United Heckathorn site. Richmond, CA.

Maruya, K.A., R.W. Riseborough, and A.J. Horne. 1996. Partitioning of polynuclear aromatic hydrocarbons between sediments from San Francisco Bay and their porewaters. *Environ. Sci. Technology 30*:2942-2947.

McPherson, C.A., E.A. Power, and P.D.S. Grindlay. 1989. Chemical characterization and bioassay testing of sediments from Richmond Harbor. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Pereira, W.E., F.D. Hostettler, and J.B. Rapp. 1996. Distributions and fate of chlorinated pesticides, biomarkers and polycyclic aromatic hydrocarbons in sediments along a contamination gradient from a point-source in San Francisco Bay, California. *Marine Environmental Research 41*(3):299-314.

Pinza, M.R., J.A. Ward, H.L. Mayhew, J.Q. Word, D.K. Niyogi, N.P. Kohn. 1992.Ecological evaluation of proposed dredged material from Richmond Harbor, California.PNL-8389. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Pinza, M.R., H.L. Mayhew, L.M. Karle, N.P. Kohn, P.J. White, J.Q. Word, L.L. Michaels. 1995a. Ecological evaluation of proposed dredged material from the Richmond Harbor deepening

project and the intensive study of the turning basin. PNL-10627. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Pinza, M.R., H.L. Mayhew, and J.Q. Word. 1995b. Evaluation of older bay mud sediment from Richmond Harbor, California. PNNL-11318. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Power, E.A. and P.M. Chapman. 1988. Analysis and bioassay testing of sediments collected from Richmond Inner Harbor. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Power, E.A. and P.M. Chapman. 1989. Mercury characterization and bioassay testing of sediments from Richmond Inner Harbor. San Francisco: U.S. Army Corps of Engineers, San Francisco District. 21 pp.

Swartz, R.C., F. Cole, J. Lamberson, S. Ferraro, D. Schultz, W. Deben, H. Lee II, and R. Ozretich. 1994. Sediment toxicity, contamination, and amphipod abundance at a DDTand Dieldrin-contaminated site in San Francisco Bay. *Oregon Environmental Toxicology and Chemistry* 13:949-962.

URS Consultants, Inc. 1994. CERCLA site inspection, Stauffer Chemical Company, AKA: ICI Americas, 1415 S. 47th Street, Richmond, CA, Contra Costa County. EPA Site No. CAD009123456, document control no. 62210.28.33.901 05.a.1, contract no. 68-W9-0054. San Francisco: U.S. Environmental Protection Agency.

USEPA. 1994. Ecological risk assessment of the marine sediments at the United Heckathorn Superfund site. Draft. Newport, Oregon: U.S. Environmental Protection Agency, Pacific Ecosystem Branch.

SAN PABLO BAY

ABT. 1994a. Results of chemical, physical, and bioassay testing for the Larkspur Ferry Terminal. Moffatt & Nichol, Engineers by MEC Analytical Systems, Inc. and Advanced Biological Testing.

Collins, J. and M. May. 1996. Contamination in tidal wetlands. *In: 1995 Annual Report San Francisco Regional Monitoring Program for Trace Substances* Richmond: San Francisco Estuary Institute.

E.A. Engineering, Science and Technology, ToxScan, TMA/Norcal Labs. 1989. Sediment chemistry and bioassays for proposed maintenance dredging at Pacific Technology Refining Company. 14 pp.

EVS Consultants. 1987. A chemical and toxicological evaluation of sediments from San Pablo Bay. San Francisco: U.S. Environmental Protection Agency.

EVS Consultants. 1989. Chemical Characterization and Bioassay Testing of Sediments from Pinole Shoal Channel. DACWO7-88-D-008. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

EVS Consultants. 1991. Chemical and toxicological analysis of sediments from Castro Cove in San Francisco Bay. Richmond, California: Richmond Refinery.

Ecology and Environment, Inc. 1983. Initial Assessment Study of Naval Shipyard, Mare Island, California. San Bruno: Navy Assessment and Control of Installation Pollutants Department.

Engineering-Science Inc. (ESI). 1993. Final Environmental Investigation Report, Hamilton Army Airfield, Volumes I and II. July.

Entrix. 1990. Surface sediment monitoring program for Castro Cove and areas adjacent to the deepwater outfall and eelgrass beds. Richmond, California: Richmond Refinery.

Hostettler, Francis D., W.E. Pereira, K.A. Kvenvolden, D.R. Jones, and F. Murphy. In Review. Preliminary geochemical studies of pollutant and natural organic compounds in sediments from Sonoma Baylands.

International Technology Corporation (IT). 1992. Distribution and environmental fate of metals and organotin in Mare Island Strait near Building 900. San Bruno: U.S. Navy.

MEC Analytical Systems Inc. (MEC). 1990. Results of bioassay analysis on sediments from the Pacific Refinery pier in San Pablo Bay. Tiburon, California: Great Lakes Dredging Company. 15 pp.

MEC. 1993. Results of chemical, physical, and bioassay testing of sediments at Bahia Lagoon. Mike Cheney Consulting.

MEC and ABT. 1994. Results of chemical, physical, and bioassay testing of sediment at the San Rafael Rock Quarry Loading Terminal. DCC Engineering. MEC Analytical Systems, Inc. and Advanced Biological Testing Inc.

Marine Bioassay Laboratories (MBL). 1987. Sediment sampling and chemical and bioassay analysis of sediments from Mare Island and Carquinez (SF-9) disposal site, San Francisco Estuary, California. San Francisco: U.S. Army Corps of Engineers, San Francisco District. 48 pp.

Ota, A.Y., L.E. Schemel, and S.W. Hager. 1986. *Physical and chemical data for Northern San Francisco Bay, CA, September-November, 1984.* U.S. Geological Survey Open-File Report 86-228. Reston, Virginia: U.S. Geological Survey. 32 pp.

PRC. 1995. No further information available.

Power, E.A., C.A. McPherson, and P.M. Chapman. 1989. Chemical characterization and bioassay testing of sediments from Mare Island. San Francisco: U.S. Army Corps of Engineers, San Francisco District. 55 pp.

Stukas, V. 1986. Trace metal profiles in the San Pablo Bay area, August 1986, using the vacuum intercept pumping system and ultraclean handling techniques. Appendix E in Chevron USA Richmond Refinery Deepwater Outfall Project, Draft EIS Report. San Francisco: U.S. Environmental Protection Agency. January 1987 Appendices.

ToxScan. 1993. Sediments at Pinole Shoal: Fiscal Year 1993 Maintenance Dredging. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

USACE. 1987. Dredged material testing. Petaluma maintenance dredging. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

USACE. 1994. Supplement to the Final Environmental Investigation Report. Hamilton Army Airfield, California.

USACE. 1996. Draft Additional Environmental Investigation Report, BRAC Property, Hamilton Army Airfield. Prepared by Woodward-Clyde Federal Services. U.S. Army Corps of Engineers.

U.S. Department of Interior. 1994. Determination of total recoverable arsenic, cadmium, copper, lead, mercury, and selenium in soil and sediment samples from San Pablo Bay, Ca. Final laboratory report FY94-32-23. Jamestown, North Dakota: National Biological Survey, Northern Prairie Science Center, Dixon Field Station.

SOUTH BAY (WITHOUT OAKLAND HARBOR)

Aqua Terra Technologies (ATT). 1991. Environmental and Sampling Analysis Plan for Naval Station, Treasure Island, Hunters Point, San Francisco, California. San Bruno: U.S. Navy.

Baumgartner, D.J. Unpublished manuscript on survey of contaminants in south San Francisco Bay. Newport, Oregon: U.S. Environmental Protection Agency, ERL-N, Hatfield Marine Science Center.

Bendix. 1987. Port of San Francisco Pier 94/96 Sediment Study. San Francisco: Port of San Francisco.

City and County of San Francisco (CCSF). 1990. Southeast and Islais Creek sediment, 1991, 1992 and 1993. San Francisco: Department of Public Works, Bureau of Water Pollution Control.

Dames & Moore. 1992. Data report, offshore sediment sampling, Army Street site, San Francisco, CA for Union Pacific Realty Co., Job No. 16515-015-043 (GN-O-111.006), Project #96231.

Ecology and Environment, Inc. (E&E). 1983. Initial Assessment Study, Naval Air Station, Alameda, California. Port Hueneme, California: Navy Assessment and Control of Installation Pollutants Department, Naval Energy and Environmental Support Activity.

EMCON Associates (EMCON). 1987. Confirmation Study Verification Step, Hunters Point Naval Shipyard (Disestablished). Volumes I-IV. San Francisco: U.S. Navy.

Environmental Science Associates (ESA). 1987a. *Final Environmental Impact Statement: Homeporting Battleship Battle group/Cruiser Destroyer Group, Volumes 1, 2, and 3*. San Bruno, California: U.S. Department of the Navy Western Division.

ESA (Environmental Science Associates, Inc.) 1987b. Supplemental testing of dredge sediments for proposed interim berthing of *U.S.S. Missouri* at Hunters Point. San Bruno, California: U.S. Department of the Navy Western Division. 11 pp.

ESA. 1988. Dredge sediment evaluation Naval Air Station, Moffett Field, Sunnyvale, CA. San Bruno, California: U.S. Department of the Navy Western Division. 77 pp.

EVS Consultants, Inc. 1989a. Draft Report of Initial Bioassay Testing of Surface Sediments for the City of Palo Alto. Seattle: J.M. Montgomery, Consulting Engineers, Inc. 50 pp.

EVS Consultants. 1989b. Chemical characterization and bioassay testing of sediments from Redwood City Harbor. Seattle: U.S. Army Corps of Engineers. 57 pp.

EVS Consultants. 1989c. Chemical charaterization and bioassay testing of resample sediments from Redwood City Harbor. Seattle: U.S. Army Corps of Engineers.

EVS Consultants. 1990a. Bioassay and chemical characterization of sediments from San Leandro Bay. Hayward, California: Alameda County Flood Control and Water District. 22 pp.

EVS Consultants, Inc. 1990b. Summary Results and Laboratory Data Sheets from the Third Sediment Bioassay Testing for the Palo Alto Regional Water Quality Control Plant. Walnut Creek, California: California Regional Water Quality Control Board. 12 pp. EVS Consultants. 1991. Draft report bioassay testing for City of Palo Alto. Seattle: Woodward-Clyde Consultants.

Harding, Lawson and Associates (HLA). 1988. Sediment evaluation Alameda Naval Air Station, Piers 2 and 3, Alameda, CA. Concord, California: Santina and Thompson, Inc.

Harding, Lawson and Associates (HLA). 1991a. Analytical data collected from the slough adjacent to Romic Chemical Corporation, East Palo Alto, Ca.

Harding, Lawson and Associates (HLA). 1991b. Preliminary Draft Ecological Risk Assessment Data Summary Report. Naval Station Treasure Island, Hunters Point Annex, San Francisco, California. San Bruno: U.S. Navy.

Harding, Lawson and Associates (HLA). 1993a. Sediment and Stormwater Sampling Data, Naval Station Treasure Island, Hunters Point Annex, San Francisco, California. San Bruno: U.S. Navy.

Harding, Lawson and Associates (HLA). 1993b. Supplemental ESAP Data Submittal, Naval Station Treasure Island, Hunters Point Annex, San Francisco, California. San Bruno: U.S. Navy.

Herman, J.M. and J.L. Cronin. 1989. Bioassay testing and chemical analysis of sediments from the Guadalupe Slough. EVS Environment Consultants, Inc., Sausalito. San Francisco: U.S. Department of the Navy Western Division, San Francisco, CA.19 pp + appendices.

Hostettler, F.D., Rapp, J.B., Kvenvolden, K.A. & Luoma, S.N. 1989. Organic markers as source discriminants and sediment transport indicators in south San Francisco Bay, California. *Geochim. Cosmochim. Acta* 54:1563-76.

Jenkins, Sanders, and Associates (JSA). 1993. An ecological assessment of the slough adjacent to Romic Facility, East Palo Alto, California. Draft final. Romic Chemical Corp.

Jenkins, Sanders, and Associates (JSA). 1994. In Situ Growth Study for Macoma balthica exposed to sediments of the slough adjacent to the Romic Facility, East Palo Alto, California. Romic Environmental Technologies Corp.

Larry Walker and Associates and Kinnetic Laboratories. 1991a. Summary data report: pollution control plant (1989 - 1990). Under contract to CH2M Hill. San Jose: City of San Jose.

Larry Walker and Associates and Kinnetic Laboratories. 1991b. Summary data report: toxicity testing of sediment collected in the vicinity of the Sunnyvale water pollution control plant (1989 - 1990). Under contract to EOA, Inc. Sunnyvale, California: City of Sunnyvale.

Luoma, S.N., D.J. Cain, C. Brown and E.V. Axtmann. 1991. Trace metals in clams (Macoma balthica) and sediments at the Palo Alto mudflat in South San Francisco Bay: April, 1990 - April, 1991. U.S. Geological Survey Open File Report 91-460. Menlo Park, California: U.S. Geological Survey. 47 pp.

Luoma, S.N., D.J. Cain, C. Brown and M. Hornberger. 1992. Trace metals in clams (Macoma balthica) and sediments at the Palo Alto mudflat in South San Francisco Bay: May 1991 - May 1992. U.S. Geological Survey Open File Report 92-456. Menlo Park, California: U.S. Geological Survey. 51 pp.

Luoma, S.N., D.J. Cain, C. Brown and M. Hornberger. 1993. Trace metals in clams (Macoma balthica) and sediments at the Palo Alto mudflat in South San Francisco Bay: June 1992 - June 1993. U.S. Geological Survey Open File Report 93-500. Menlo Park, California: U.S. Geological Survey. 52 pp.

Luoma, S.N., D.J. Cain, C. Brown, M. Hornberger and R.B. Schaenemann. 1995. Near field receiving water monitoring of trace metals in clams (Macoma balthica) and sediments near the Palo Alto and San Jose/Sunnyvale water quality control plants in south San Francisco Bay: June 1993 through October 1994. U.S. Geological Survey Open File Report 95-299. Menlo Park, California: U.S. Geological Survey.

Luoma, S.N., D.J. Cain, C. Brown, M. Hornberger and R. Bouse. 1996. Near field receiving water monitoring of trace metals in clams (Macoma balthica) and sediments near the Palo Alto and San Jose/Sunnyvale water quality control plants in south San Francisco Bay: December 1994 through December 1995. U.S. Geological Survey Open File Report 96-203. Menlo Park, California: U.S. Geological Survey.

MEC. 1990. Results of chemical, physical, and bioassay analysis on sediments from the proposed Shearwater Marina.

MEC. 1994. Results of physical, chemical, and biological testing of sediments from the Naval Air Station - Alameda. Draft copy. San Bruno, California: U.S. Navy, Engineering Field Activity West.

Marine Bioassay Laboratories. 1987. Reassessment of sediment chemistry and toxicity for proposed interim berthing of the battleship U.S.S. Missouri at Hunters Point. San Francisco: Environmental Science Associates, Inc. 53 pp.

Mark Group. 1989. San Bruno Channel fill investigation, South San Francisco, CA. Text and drawings, Vol. I of II.

PRC Environmental Management, Inc. (PRC). 1991. CLEAN (West Beach Landfill and Runway Areas). NAS Alameda. San Bruno: U.S. Navy, Western Division, Naval Facilities Engineering Command.

PRC Environmental Management, Inc. (PRC). 1994. Naval Air Station Alameda Draft Ecological Assessment. Feb 17 1994. Draft Report Amendment, July 1 1994. San Bruno, California: U.S. Navy, Engineering Field Activity West.

PRC Environmental Management, Inc. 1996. Hunters Point Shipyard, Phase 1B Ecological Risk Assessment. Draft. Vol. 1 and 11. San Bruno, California: U.S. Navy, Engineering Field Activity West.

PTI. 1994. Supplemental inshore sediment impairment study. Crowley Marine Services, Inc. Pacific Drydock Yards I & II, June, 1994. Volume I.

Power, E.A. and P.M. Chapman. 1988. Analyses and bioassay testing of sediments collected from San Francisco Harbor approaches to Piers 80 and 94. EVS Environment Consultants, Inc., Seattle, Washington. U.S. Army Corps of Engineers, C District M/F. 23 pp + appendices.

SFBRWQCB. 1986. South Bay Dischargers Authority, Santa Clara County - status report on five-year monitoring program. Executive officer summary report. San Francisco: San Francisco Bay Regional Water Quality Control Board.

San Francisco Port Commission (SFPC). 1988. Maintenance dredging testing results. San Francisco: Port of San Francisco. 160 pp.

San Francisco Port Commission (SFPC). 1990. Maintenance dredging testing results 1990. San Francisco: Port of San Francisco. 87pp.

Spies, R.B. 1987. Relationships between bioassays, contaminant concentrations in sediments and bioavailability of contaminants from San Francisco Bay sediments. A report on pre-dredging studies for the homeporting of the U.S.S. Missouri. San Francisco: Environmental Science Associates. 42 pp.

Stevenson, M.L., T.C. Goddard, L.M. Kiguchi, and P.J. Kinney. 1987. South Bay Dischargers Authority water quality monitoring program: final monitoring report, December 1981-November 1986. Santa Cruz: South Bay Dischargers Authority, 467 pp.

ToxScan. 1989a. Toxicity testing of sediment collected in the vicinity of the San Jose/Santa Clara Waste Treatment Plant. San Jose: Cities of San Jose and Santa Clara. 24 pp.

ToxScan. 1989b. Toxicity testing of sediment collected in the vicinity of the Sunnyvale Waste Treatment Plant. Sunnyvale, California: City of Sunnyvale. 23 pp.

ToxScan. 1990. Toxicity testing of sediment collected in the vicinity of the Sunnyvale Waste Treatment Plant. CH2M Hill. 25 pp.

Treadwell & Rollo. 1995. Advanced Biological Testing. Oyster Point Shearwater Project. Proposed Sampling Locations. South San Francisco.

Wahler Associates. 1985. Draft Report, Verification Step, Confirmation Study. NAS Alameda. San Bruno: U.S. Navy Western Division, Naval Facilities Engineering Command.

OAKLAND HARBOR

Environmental Science Associates (ESA). 1987. Chemical and bioassay testing of sediments: Oakland Naval Supply Center/Alameda Naval Air Station. San Bruno: U.S. Navy, Western Division, Naval Facilities Engineering Command.

Environmental Science Associates (ESA). 1988a. Military construction project (P-082) naval dredging middle harbor, Naval Supply Center, Oakland, environmental assessment. San Bruno: U.S. Navy, Western Division, Naval Facilities Engineering Command.

Environmental Science Associates (ESA). 1988b. Military construction project (P-202) naval dredging piers 2 and 3, Naval Supply Center, Oakland, environmental assessment. San Bruno: U.S. Navy, Western Division, Naval Facilities Engineering Command.

Environmental Science Associates (ESA). 1988c. Dredge sediment evaluation - Naval Air Station, Alameda. San Bruno: U.S. Navy, Western Division, Naval Facilities Engineering Command.

Harding Lawson Associates. 1988a. Sediment evaluation Naval Supply Center Piers 4 and 5, Oakland, California. Oakland: Vickerman Zachery Miller.

Harding Lawson Associates. 1988b. Sediment evaluation Alameda Naval Air Station Piers 2 and 3, Alameda, California. Concord, California: Santina and Thompson, Inc.

Herman, J.M., Dexter, R.N., Smith, B.M. 1991. Bioassay, Bioaccumulation and Chemical Testing of Sediments from Oakland Inner and Outer Harbor. EVS Consultants, Inc. San Francisco: U.S. Army Corps of Engineers-San Francisco District, San Francisco, California.

Karle L.M., W.W. Gardiner, and J.Q. Word. 1993. Letter Report. Ecological evaluation of Oakland Inner Harbor 38-foot channel maintenance sediments. Battelle Northwest Laboratories. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Kohn, N.P., H.L. Mayhew, J.A. Ward, N.A. Cadoret, J.Q. Word. 1992a. Ecological evaluation of proposed dredged material from Oakland Harbor berthing areas. Battelle/Marine Sciences Laboratory. Oakland: Port of Oakland.

Kohn, N.P., J.A. Ward, H.L. Mayhew, J.Q. Word, E.S. Barrows, S.M. Goodwin, L.F.Lefkovitz. 1992b. Ecological evaluation of proposed discharge of dredged material fromOakland Harbor into ocean waters (Phase IIIB of 42-foot project). PNL-8174. Battelle/MarineSciences Laboratory. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Kohn, N.P., W.W. Gardiner, R.K. Karls, P.J. White, J.A. Ward. 1994a. Evaluation of 1994 proposed maintenance dredged material from Oakland Harbor Berth 20, Berth 21, Berth 23, Berth 24, Berth 25, Berths 60-63, and Berths 67-68. Battelle Northwest Laboratories. Oakland: Port of Oakland.

Kohn, N.P., W.W. Gardiner, R.K. Karls, P.J. White, J.A. Ward. 1994b. Evaluation of proposed deepening dredged material from Oakland Harbor Berth 23, Berth 24, and Berths 60-63. PNWD-2270. Battelle Northwest Laboratories. Oakland: Port of Oakland.

Kohn, N.P., W.W. Gardiner, P.J. White. 1994c. Evaluation of 1994 proposed maintenance dredged material from Oakland Harbor Berths 26 and 30, and Oakland outer harbor channel. PNWD-2270. Battelle Northwest Laboratories. Oakland: Port of Oakland.

Kohn, N.P., W.W. Gardiner, M.R. Pinza, P.J. White. 1995a. Evaluation of 1995 proposed maintenance dredged material from Oakland Harbor Berths 25, 26, 30 and 37. PNWD-2319. Battelle Northwest Laboratories. Oakland: Port of Oakland.

Kohn, N.P., W.W. Gardiner, M.R. Pinza, P.J. White. 1995b. Evaluation of 1995 proposed maintenance dredged material from Oakland Harbor Berths 22, 23, 24, 35, 67, and 68. PNWD-2333. Battelle Northwest Laboratories. Oakland: Port of Oakland.

Kohn, N.P., W.W. Gardiner, P.J. White. 1996. Evaluation of 1995 proposed deepening dredged material from Oakland Harbor Berths 22, 23, 24, 25, and 26. PNWD-2342. Battelle/Marine Sciences Laboratory. Oakland: Port of Oakland.

MEC. 1990a. Results of chemical, physical, and bioassay analysis on subsurface sediments from Berth 35 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990b. Results of chemical, physical, and bioassay analysis on surface sediments from Berth 36 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990c. Results of chemical, physical, and bioassay analysis on sediments from Berth 20 Port of Oakland. City: Port of Oakland.

MEC. 1990d. Results of chemical, physical, and bioassay analysis on sediments from Berth 24 Port of Oakland. Oakland: Port of Oakland, MEC. 1990e. Results of chemical, physical, and bioassay analysis on sediments from Berth 32 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990f. Results of chemical, physical, and bioassay analysis on sediments from Berth 33 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990g. Results of chemical, physical, and bioassay analysis on sediments from Berth 22 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990h. Results of chemical, physical, and bioassay analysis on maintenance dredging sediments from Berths 30/31 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990i. Results of chemical, physical, and bioassay analysis on sediments from Berth 23 Port of Oakland. Oakland: Port of Oakland, Oakland.

MEC. 1990j. Results of chemical, physical, and bioassay analysis on sediments from Berth 22 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990k. Results of chemical, physical, and bioassay analysis on sediment from Berth 33 Port of Oakland. Oakland: Port of Oakland.

MEC. 1990l. Results of chemical, physical, and bioassay analysis on dredge sediments from Berths 60 to 63 American President Lines Port of Oakland. Oakland: American President Lines.

Mayhew, H.L., J.Q. Word, N.P. Kohn, M.R. Pinza, J.A. Ward. 1992. Ecological evaluation of Oakland Harbor Phase III 38-Foot composites relative to the Alcatraz Island environs (R-AM). San Francisco: U.S. Army Corps of Engineers, San Francisco District. Battelle/Marine Sciences Laboratory. Pacific Northwest Laboratory, Richland, WA.

McPherson, C.A., E.A. Power, and P.M. Chapman. 1989. Chemical characterization and bioassay testing of sediments from Oakland Harbor. San Francisco: U.S. Army Corps of Engineers, San Francisco District. PTI. 1994. Supplemental inshore sediment impairment study. Crowley Marine Services, Inc. Pacific Drydock Yards I & II, June, 1994. Volume I.

Pinza, M.R., H.L.Mayhew, L.M. Karle, J.Q. Word. 1993. Ecological evaluation of proposed dredged material from the Oakland Harbor intensive study, IC-1 and OC4-B. PNL-8933. Battelle/Marine Sciences Laboratory. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Power, E.A., and P.M. Chapman. 1988a. Analysis and Bioassay Testing of Sediments Collected from Oakland Inner Harbor. EVS Project No. 2/274-08.2. San Francisco: U.S. Army Corps of Engineers-San Francisco District.

Power, E.A., and P.M. Chapman. 1988b. Analysis and Bioassay Testing of Sediments Collected from Oakland Outer Harbor. EVS Project No. 2/274-08.3. San Francisco: U.S. Army Corps of Engineers.

Smith, B.M, Dexter, R.N. Herman, J.M., J. Crowley. 1991. Bioassay, Bioaccumulation, and Chemical Testing of Sediments from Oakland Inner and Outer Harbor. EVS Consultants, Inc. San Francisco: U.S. Army Corps of Engineers-San Francisco District.

USACE. 1988. Oakland Harbor deep-draft navigation improvements design, Memorandum no. 1. General design and final supplement I to the Environmental Impact Statement. San Francisco: U.S. Army Corps of Engineers.

Ward, J.A., J.Q. Word, M.R. Pinza, H.L. Mayhew, E.S. Barrows, and L.K. Lefkovitz. 1992a. Ecological evaluation of proposed discharge of dredged material from Oakland Harbor into ocean waters (Phase III of 38-foot project). EVS Consultants, Inc. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Ward, J.A., J.Q. Word, M.R. Pinza, H.L. Mayhew, E.S. Barrows, and L.K. Lefkovitz. 1992b. Ecological evaluation of proposed discharge of dredged material from Oakland Harbor into ocean waters (Phase IIIA of -42-foot project). PNL-8302. Battelle/Marine Sciences Laboratory. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Word, J.Q., J.A. Ward, C.W. Apts, D.L. Woodruff, M.E. Barrows, V.I. Cullinan, J.L. Hyland, and J.F. Campbell. 1988. Confirmatory sediment analyses and solid and suspended particulate

phase bioassays on sediment from Oakland Inner Harbor, San Francisco, California. PNL-7686. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Word, J.Q., J.A. Ward, J.A. Strand, V.I. Cullinan, E.A. Crecelius, W. Steinhauer, and J.L. Hyland. 1990a. Ecological evaluation of proposed discharge of dredged material from Oakland Harbor into ocean waters (Phase I of -42-Foot Project). EVS Consultants, Inc. PNL-7484. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Word, J.Q., J.A. Ward, J.A. Strand, N.P. Kohn, and A.L. Squires. 1990b. Ecological evaluation of proposed discharge of dredged material from Oakland Harbor into ocean waters (Phase II of -42-Foot Project). PNL-7483. EVS Consultants, Inc. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Word, J.Q., J.A. Ward, D.L. Woodruff. 1990c. Results of Bulk Sediment Analysis and Bioassay Testing on Selected Sediments from Oakland Inner Harbor and Alcatraz Disposal Site. EVS Consultants, Inc. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Versar, Inc. 1992. Revised Inshore Sediment Impairment Study, Pacific Dry Dock and Repair Yard II, Oakland, California. Crowley Maritime Corporation. 21 pp. + appendices.

SUISUN BAY

ABT (Advanced Biological Testing Inc.) 1994a. Results of chemical, physical, and bioassay testing of sediments at Benicia Industries' Wharf in the Port of Benicia. Advanced Biological Testing Inc. May. Mike Cheney, USA.

ABT. 1994b. Results of chemical, physical, and bioassay testing of sediments at Wickland Oil Company Benicia Loading Terminal. September. Wickland Oil Martinez.

ABT. 1995. Results of chemical, physical and bioassay testing of sediments at Exxon Benicia Refinery Bulk Loading Pier. Advanced Biological Testing Inc. Exxon Company, USA.

CH2M-Hill and Alex Horne Associates. 1986. Equivalent Protection Study for Stauffer Chemical Company, Martinez Sulfuric Acid Plan. Martinez, CA. Martinez, California: Stauffer Chemical. Domagalski, J.L., and Kuivila, K.M. 1993. Distribution of pesticides and organic contaminants between water and suspended sediment, San Francisco Bay, California. *Estuaries 16*(3A):416-426.

EVS Consultants. 1990. Bioassay and chemical testing of sediments from Suisun Channel Slough and Pierce Island upland disposal site. 105 pp.

International Technology Corporation (IT Corporation). 1992. Site Investigation of the Tidal Area. Concord, California: Naval Weapons Facility.

Kohn, N.P., P.J. White, W.W. Gardiner, and J.Q. Word. 1994. Ecological evaluation of proposed dredged material from Bulls Head Channel (lower Suisun Bay). Battelle/Pacific Northwest Laboratory. San Francisco: U.S. Army Corps of Engineers, San Francisco District.

Lee, C.R., et al. 1988. *Remedial Investigation of Contaminant Mobility at Naval Weapons Station, Concord, California; Subtitle Appendix 2.5 - 1986/87 Data.* Miscellaneous Paper EL-86-2. Vicksburg: U.S. Army Engineer Waterways Experiment Station.

Levine Fricke. 1992. Dredging interim remedial measure for the period September 11 through November 7, 1991. Selby Slag site, Selby, California. Wickland Oil Company. 12 pp + appendices.

Luoma, S.N., P.V. Cascos, and R.M. Dagovitz. 1984. *Trace metals in Suisun Bay, California*. U.S. Geological Survey Water Investigations Report 84-4170. Menlo Park, California: U.S. Geological Survey.

Luoma, S.N., R. Dagovitz, and E. Axtmann. 1987. *Trace metals in sediments and the bivalve Corbicula sp. from the Suisun Bay/San Joaquin Delta of San Francisco Bay.* Menlo Park, California: U.S. Geological Survey.

Luoma, S.N., R. Dagovitz, and E. Axtmann. 1990. Temporally intensive study of trace metals in sediments and bivalves from a large river-estuarine system: Suisun Bay/Delta in San Francisco Bay. *Sci. Total Environ.* 97(98):685-712.

MEC. 1990. Results of chemical, physical, and bioassay tests of sediments from the Unocal Marine Terminal. Unocal Corporation. 56 pp.

PRC. 1996a. Interim Draft Remedial Investigation Report. Tidal Area Sites. Volume 1. Naval Weapons Station. Concord, California. San Bruno, California: U.S. Navy, Naval Facilities Engineering Command.

PRC. 1996b. Draft Qualitative Ecological Assessment Report. Litigation Area. Naval Weapons Station Concord, California. San Bruno, California: U.S. Navy, Naval Facilities Engineering Command.

SFBRWQCB. 1987. Selby Slag site, Contra Costa County. *Status report on pollution investigation and site remediation plans, executive officer summary report.* San Francisco: San Francisco Bay Regional Water Quality Control Board.